

62838: 12/23/17 00:43:27 0/0: SEV, syslog, Dec 23 02:43:27.637: %UBR10KTCC-1-LCLOSC: Cable Line Card 5/1 using the local oscillator

62839: 12/23/17 00:43:25 0/0: SEV, syslog, Dec 23 02:43:25.089: %UBR10KTCC-1-LCLOSC: Cable Line Card 5/0 using the local oscillator

62840: 12/23/17 00:43:04 0/0: SEV, syslog, Dec 23 02:43:04.897: %UBR10KTCC-1-NOTCC: No working TCC card available in the system

62841: 12/23/17 00:42:27 0/0: SEV, syslog, Dec 23 02:42:27.608: %UBR10KTCC-1-LCLOSC: Cable Line Card 5/1 using the local oscillator

62842: 12/23/17 00:42:25 0/0: SEV, syslog, Dec 23 02:42:25.060: %UBR10KTCC-1-LCLOSC: Cable Line Card 5/0 using the local oscillator

62843: 12/23/17 00:41:41 0/0: MAJ, syslog, Dec 23 02:41:41.328: %IPCOIR-2-CARD UP DOWN: Card in slot 2/1 is down. Notifying 2cable-dtcc driver.

62844: 12/23/17 00:41:41 0/0: MAJ, syslog, Dec 23 02:41:41.328: %IPCOIR-3-TIMEOUT: Timeout waiting for a response from slot 2/1.

62845: 12/23/17 00:41:27 0/0: SEV, syslog, Dec 23 02:41:27.580: %UBR10KTCC-1-LCLOSC: Cable Line Card 5/1 using the local oscillator

62846: 12/23/17 00:41:25 0/0: SEV, syslog, Dec 23 02:41:25.032: %UBR10KTCC-1-LCLOSC: Cable Line Card 5/0 using the local oscillator

62847: 12/21/17 08:02:45 0/0: MAJ, syslog, Dec 21 10:02:45.408: %IPCOIR-2-CARD UP DOWN: Card in slot 2/1 is up. Notifying 2cable-dtcc driver.

62848: 12/21/17 08:02:45 0/0: MAJ, syslog, SLOT 5/0: Dec 21 10:02:44.308: %INTR_MGR-3-INTR: SLOT 5/0 - Corabi IOFPGA: TimeStamp Parity Error

62849: 12/21/17 08:02:45 0/0: MAJ, syslog, SLOT 5/1: Dec 21 10:02:44.308: %INTR_MGR-3-INTR: SLOT 5/1 - Corabi IOFPGA: TimeStamp Parity Error

62850: 12/21/17 08:02:33 0/0: MAJ, syslog, Dec 21 10:02:33.256: %IPCOIR-2-CARD UP DOWN: Card in slot 2/1 is down. Notifying 2cable-dtcc driver.

62851: 12/21/17 08:02:33 0/0: MAJ, syslog, Dec 21 10:02:33.256: %IPCOIR-3-TIMEOUT: Timeout waiting for a response from slot 2/1.

62852: 12/20/17 08:03:21 0/0: MAJ, syslog, Dec 20 10:03:21.574: %IPCOIR-2-CARD UP DOWN: Card in slot 1/1 is down. Notifying 2cable-dtcc driver.

62853: 12/20/17 08:03:21 0/0: MAJ, syslog, Dec 20 10:03:21.574: %IPCOIR-3-TIMEOUT: Timeout waiting for a response from slot 1/1.

62854: 12/15/17 11:08:39 0/0: MOD, BfLkMon, Resource 'Net Background' holding 8242 (vs. 7887) old IO buffers.

62855: 12/15/17 11:08:39 0/0: MOD, MemMon, [I/O] 67% Mem Free. Free 112778284, Total 167772156, Lowest 112778284. low_mem_trend=32 (of 60).

62856: 12/15/17 09:08:38 0/0: MOD, BfLkMon, Resource 'Net Background' holding 7887 (vs. 7167) old IO buffers.

62857: 12/15/17 09:08:38 0/0: MOD, MemMon, [I/O] 67% Mem Free. Free 112897516, Total 167772156, Lowest 112897516. low_mem_trend=59 (of 60).

62858: 12/15/17 07:08:36 0/0: MOD, BfLkMon, Resource 'Net Background' holding 7167 (vs. 6447) old IO buffers.

62859: 12/15/17 07:08:36 0/0: MOD, MemMon, [I/O] 67% Mem Free. Free 113128348, Total 167772156, Lowest 113128348. low_mem_trend=59 (of 60).

62860: 12/15/17 05:08:34 0/0: MOD, BfLkMon, Resource 'Net Background' holding 6447 (vs. 5726) old IO buffers.

62861: 12/15/17 05:08:34 0/0: MOD, MemMon, [I/O] 67% Mem Free. Free 113359628, Total 167772156, Lowest 113359628. low_mem_trend=58 (of 60).

62862: 12/15/17 03:08:33 0/0: MOD, BfLkMon, Resource 'Net Background' holding 5726 (vs. 5006) old IO buffers.

62863: 12/15/17 03:08:33 0/0: MOD, MemMon, [I/O] 67% Mem Free. Free 113590012, Total 167772156, Lowest 113590012. low_mem_trend=58 (of 60).

62864: 12/15/17 01:08:31 0/0: MOD, BfLkMon, Resource 'Net Background' holding 5006 (vs. 4286) old IO buffers.

62865: 12/15/17 01:08:31 0/0: MOD, MemMon, [I/O] 67% Mem Free. Free 113818684, Total 167772156, Lowest 113818684. low_mem_trend=59 (of 60).

62866: 12/14/17 23:08:30 0/0: MOD, BfLkMon, Resource 'Net Background' holding 4286 (vs. 3566) old IO buffers.

62867: 12/14/17 23:08:30 0/0: MOD, MemMon, [I/O] 67% Mem Free. Free 114052540, Total 167772156, Lowest 114052540. low_mem_trend=59 (of 60).

62868: 12/14/17 21:08:28 0/0: MOD, BfLkMon, Resource 'Net Background' holding 3566 (vs. 2846) old IO buffers.

62869: 12/14/17 21:08:28 0/0: MOD, MemMon, [I/O] 68% Mem Free. Free 114281580, Total 167772156, Lowest 114281580. low_mem_trend=59 (of 60).

62870: 12/14/17 19:08:27 0/0: MOD, BfLkMon, Resource 'Net Background' holding 2846 (vs. 2126) old IO buffers.

62871: 12/14/17 19:08:27 0/0: MOD, MemMon, [I/O] 68% Mem Free. Free 114513980, Total 167772156, Lowest 114513980. low_mem_trend=58 (of 60).

62872: 12/14/17 17:08:25 0/0: MOD, BfLkMon, Resource 'Net Background' holding 2126 (vs. 1406) old IO buffers.

62873: 12/14/17 17:08:25 0/0: MOD, MemMon, [I/O] 68% Mem Free. Free 114744300, Total 167772156, Lowest 114744300. low_mem_trend=58 (of 60).

62874: 12/14/17 15:08:23 0/0: MOD, BfLkMon, Resource 'Net Background' holding 1406 (vs. 698) old IO buffers.

62875: 12/14/17 15:08:23 0/0: MOD, MemMon, [I/O] 68% Mem Free. Free 114975452, Total 167772156, Lowest 114975452. low_mem_trend=58 (of 60).

62876: 12/14/17 11:13:46 0/0: MAJ, syslog, .Dec 14 13:13:46.276: %LINK-3-UPDOWN: Interface Integrated-Cable5/1/2:3, changed state to up

62877: 12/14/17 11:13:46 0/0: MAJ, syslog, .Dec 14 13:13:46.272: %LINK-3-UPDOWN: Interface Integrated-Cable5/1/2:2, changed state to up

62878: 12/14/17 11:13:46 0/0: MAJ, syslog, .Dec 14 13:13:46.268: %LINK-3-UPDOWN: Interface Integrated-Cable5/1/2:1, changed state to up

62879: 12/14/17 11:13:46 0/0: MAJ, syslog, .Dec 14 13:13:46.264: %LINK-3-UPDOWN: Interface Integrated-Cable5/1/2:0, changed state to up

62880: 12/14/17 11:13:46 0/0: MAJ, syslog, .Dec 14 13:13:46.260: %LINK-3-UPDOWN: Interface Integrated-Cable5/1/1:3, changed state to up

62881: 12/14/17 11:13:46 0/0: MAJ, syslog, .Dec 14 13:13:46.256: %LINK-3-UPDOWN: Interface Integrated-Cable5/1/1:2, changed state to up

62882: 12/14/17 11:13:46 0/0: MAJ, syslog, .Dec 14 13:13:46.248: %LINK-3-UPDOWN: Interface Integrated-Cable5/1/1:1, changed state to up

62883: 12/14/17 11:13:46 0/0: MAJ, syslog, .Dec 14 13:13:46.244: %LINK-3-UPDOWN: Interface Integrated-Cable5/1/1:0, changed state to up

62884: 12/14/17 11:13:46 0/0: MAJ, syslog, .Dec 14 13:13:46.240: %LINK-3-UPDOWN: Interface Integrated-Cable5/1/0:3, changed state to up

62885: 12/14/17 11:13:46 0/0: MAJ, syslog, .Dec 14 13:13:46.236: %LINK-3-UPDOWN: Interface Integrated-Cable5/1/0:2, changed state to up

62886: 12/14/17 11:13:46 0/0: MAJ, syslog, .Dec 14 13:13:46.232: %LINK-3-UPDOWN: Interface Integrated-Cable5/1/0:1, changed state to up

62887: 12/14/17 11:13:46 0/0: MAJ, syslog, .Dec 14 13:13:46.228: %LINK-3-UPDOWN: Interface Integrated-Cable5/1/0:0, changed state to up

62888: 12/14/17 11:13:41 0/0: MAJ, syslog, .Dec 14 13:13:41.808: %LINK-3-UPDOWN: Interface Integrated-Cable5/0/2:3, changed state to up

62889: 12/14/17 11:13:41 0/0: MAJ, syslog, .Dec 14 13:13:41.804: %LINK-3-UPDOWN: Interface Integrated-Cable5/0/2:2, changed state to up
62890: 12/14/17 11:13:41 0/0: MAJ, syslog, .Dec 14 13:13:41.800: %LINK-3-UPDOWN: Interface Integrated-Cable5/0/2:1, changed state to up
62891: 12/14/17 11:13:41 0/0: MAJ, syslog, .Dec 14 13:13:41.796: %LINK-3-UPDOWN: Interface Integrated-Cable5/0/2:0, changed state to up
62892: 12/14/17 11:13:41 0/0: MAJ, syslog, .Dec 14 13:13:41.780: %LINK-3-UPDOWN: Interface Integrated-Cable5/0/1:3, changed state to up
62893: 12/14/17 11:13:41 0/0: MAJ, syslog, .Dec 14 13:13:41.776: %LINK-3-UPDOWN: Interface Integrated-Cable5/0/1:2, changed state to up
62894: 12/14/17 11:13:41 0/0: MAJ, syslog, .Dec 14 13:13:41.768: %LINK-3-UPDOWN: Interface Integrated-Cable5/0/1:1, changed state to up
62895: 12/14/17 11:13:41 0/0: MAJ, syslog, .Dec 14 13:13:41.764: %LINK-3-UPDOWN: Interface Integrated-Cable5/0/1:0, changed state to up
62896: 12/14/17 11:13:41 0/0: MAJ, syslog, .Dec 14 13:13:41.728: %LINK-3-UPDOWN: Interface Integrated-Cable5/0/0:3, changed state to up
62897: 12/14/17 11:13:41 0/0: MAJ, syslog, .Dec 14 13:13:41.712: %LINK-3-UPDOWN: Interface Integrated-Cable5/0/0:2, changed state to up
62898: 12/14/17 11:13:41 0/0: MAJ, syslog, .Dec 14 13:13:41.708: %LINK-3-UPDOWN: Interface Integrated-Cable5/0/0:1, changed state to up
62899: 12/14/17 11:13:41 0/0: MAJ, syslog, .Dec 14 13:13:41.704: %LINK-3-UPDOWN: Interface Integrated-Cable5/0/0:0, changed state to up
62900: 12/14/17 11:13:38 0/0: MAJ, syslog, .Dec 14 13:13:38.576: %LINK-3-UPDOWN: Interface Cable5/1/4, changed state to up
62901: 12/14/17 11:13:36 0/0: MAJ, syslog, .Dec 14 13:13:36.600: %IPCOIR-2-CARD_UP_DOWN: Card in slot 5/1 is up. Notifying ubr10k-clc-mc2020v driver.
62902: 12/14/17 11:13:36 0/0: MAJ, syslog, .Dec 14 13:13:36.028: %LINK-3-UPDOWN: Interface Wideband-Cable5/1/0:0, changed state to up
62903: 12/14/17 11:13:35 0/0: MAJ, syslog, .Dec 14 13:13:35.592: %LINK-3-UPDOWN: Interface Cable5/0/4, changed state to up

62904: 12/14/17 11:13:33 0/0: MAJ, syslog, .Dec 14 13:13:33.616: %IPCOIR-2-CARD_UP_DOWN: Card in slot 5/0 is up. Notifying ubr10k-clc-mc2020v driver.

62905: 12/14/17 11:13:31 0/0: MAJ, syslog, .Dec 14 13:13:31.684: %LINK-3-UPDOWN: Interface Wideband-Cable5/0/0:1, changed state to up

62906: 12/14/17 11:13:31 0/0: MAJ, syslog, .Dec 14 13:13:31.680: %LINK-3-UPDOWN: Interface Wideband-Cable5/0/0:0, changed state to up

62907: 12/14/17 11:13:31 0/0: MAJ, syslog, .Dec 14 13:13:31.676: %LINK-3-UPDOWN: Interface Cable5/0/4, changed state to down

62908: 12/14/17 11:13:31 0/0: MAJ, syslog, .Dec 14 13:13:31.676: %LINK-3-UPDOWN: Interface Cable5/0/3, changed state to down

62909: 12/14/17 11:13:31 0/0: MAJ, syslog, .Dec 14 13:13:31.676: %LINK-3-UPDOWN: Interface Cable5/0/2, changed state to down

62910: 12/14/17 11:13:31 0/0: MAJ, syslog, .Dec 14 13:13:31.676: %LINK-3-UPDOWN: Interface Cable5/0/1, changed state to down

62911: 12/14/17 11:11:20 0/0: MAJ, syslog, *Dec 14 13:11:20.372: %LINK-3-UPDOWN: Interface GigabitEthernet3/2/1, changed state to up

62912: 12/14/17 11:11:16 0/0: MAJ, syslog, *Dec 14 13:11:16.144: %SYS-3-HARIKARI: Process CR10K DTI upgrade process top-level routine exited

62913: 12/14/17 11:11:07 0/0: MAJ, syslog, *Dec 14 13:11:07.344: %IPCOIR-2-CARD UP DOWN: Card in slot 2/1 is up. Notifying 2cable-dtcc driver.

62914: 12/14/17 11:11:06 0/0: MAJ, syslog, *Dec 14 13:11:06.760: %C10K-3-LC_ERR: Slot[3/0] 4jacket-1

62915: 12/14/17 11:10:57 0/0: MAJ, syslog, *Dec 14 13:10:57.768: %IPCOIR-2-CARD_UP_DOWN: Card in slot 3/0 is up. Notifying 4jacket-1 driver.

62916: 12/14/17 11:10:48 0/0: MAJ, syslog, *Dec 14 13:10:48.244: %IPCOIR-2-CARD UP DOWN: Card in slot 1/1 is up. Notifying 2cable-dtcc driver.

62917: 12/14/17 11:10:36 0/0: MAJ, syslog, *Dec 14 13:10:36.824: %LINK-3-UPDOWN: Interface HTDP0/0/1, changed state to up

62918: 12/14/17 11:10:34 0/0: MAJ, syslog, *Dec 14 13:10:34.928: %LINK-3-UPDOWN: Interface Wideband-Cable5/1/0:0, changed state to down

62919: 12/14/17 11:10:34 0/0: MAJ, syslog, *Dec 14 13:10:34.856: %LINK-3-UPDOWN: Interface Cable5/1/0, changed state to down

62920: 12/14/17 11:10:34 0/0: MAJ, syslog, *Dec 14 13:10:34.856: %LINK-3-UPDOWN: Interface Wideband-Cable5/0/0:1, changed state to down

62921: 12/14/17 11:10:34 0/0: MAJ, syslog, *Dec 14 13:10:34.856: %LINK-3-UPDOWN: Interface Wideband-Cable5/0/0:0, changed state to down

62922: 12/14/17 11:10:34 0/0: MAJ, syslog, *Dec 14 13:10:34.796: %LINK-3-UPDOWN: Interface Cable5/0/0, changed state to down

62923: 12/14/17 11:10:34 0/0: MAJ, syslog, *Dec 14 13:10:34.796: %LINK-3-UPDOWN: Interface Bundle1, changed state to up

62924: 12/14/17 11:10:33 0/0: MAJ, syslog, *Dec 14 13:10:33.468: %IPCOIR-3-CARD_GET_VERSION_RESPONSE: Unsolicited response from slot 3/0, oir_state = empty

62925: 12/14/17 11:10:27 0/0: MAJ, syslog, *Dec 14 13:10:27.599: %REDUNDANCY-3-STANDBY_LOST: Standby processor fault (PEER_DOWN)

62926: 12/14/17 11:10:27 0/0: MAJ, syslog, *Dec 14 13:10:27.599: %REDUNDANCY-3-STANDBY_LOST: Standby processor fault (PEER_NOT_PRESENT)

62927: 12/14/17 11:04:59 0/0: SEV, syslog, Dec 14 13:04:59.402: %UBR10KTCC-1-LCLOSC: Cable Line Card 5/1 using the local oscillator

62928: 12/14/17 11:04:57 0/0: SEV, syslog, Dec 14 13:04:57.814: %UBR10KTCC-1-LCLOSC: Cable Line Card 5/0 using the local oscillator

62929: 12/14/17 11:03:59 0/0: SEV, syslog, Dec 14 13:03:59.205: %UBR10KTCC-1-LCLOSC: Cable Line Card 5/1 using the local oscillator

62930: 12/14/17 11:03:57 0/0: SEV, syslog, Dec 14 13:03:57.641: %UBR10KTCC-1-LCLOSC: Cable Line Card 5/0 using the local oscillator